

pH Readings for Former Lime Property						
Date	Time	Media	Area Description	Latitude	Longitude	pH Field Reading
10/17/2016	1633	Visual	Pond North of Trail	38.7027	-120.819	-
10/17/2016	1655	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.701443	-120.814311	-
11/15/2016	1317	Water	Pond North of Trail	38.7027	-120.819	12.42
11/15/2016	1331	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.701443	-120.814311	-
11/21/2016	1406	Water	Pond North of Trail	38.7027	-120.819	12.53
11/21/2016	1414	Water	Drainage South of Trail	38.7026	-120.8183	8.26
11/21/2016	1423	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.17
11/21/2016	1425	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.22
11/21/2016	1435	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.50
11/21/2016	1436	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 53	38.7018	-120.8145	12.13
11/21/2016	1438	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
12/29/2016	1224	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	13.52
12/29/2016	-	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 53	38.7018	-120.8145	-
12/29/2016	-	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
12/29/2016	1240	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	10.58
12/29/2016	1245	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.53
12/29/2016	1250	Water	Pond North of Trail	38.7027	-120.819	13.31
12/29/2016	1255	Water	Drainage South of Trail	38.7026	-120.8183	8.85
1/26/2017	1430	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	12.86
1/26/2017	1440	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	13.34
1/26/2017	1444	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	13.1
1/26/2017	1447	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	13.28
1/26/2017	1501	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	9.23
1/26/2017	1502	Water	Drainage South of Trail	38.7026	-120.8183	9.02
1/26/2017	1505	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	9.1
1/26/2017	1509	Water	Pond North of Trail	38.7027	-120.819	13.36
3/17/2017	1445	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	11.95
3/17/2017	1433	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
3/17/2017	1433	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
3/17/2017	1438	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.64
3/17/2017	1458	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.43
3/17/2017	1506	Water	Drainage South of Trail	38.7026	-120.8183	8.42

3/17/2017	1508	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.55
3/17/2017	1512	Water	Pond North of Trail	38.7027	-120.819	12.69
4/21/2017	1553	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	12.02
4/21/2017	1532	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	12.66
4/21/2017	1532	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
4/21/2017	1543	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.56
4/21/2017	1608	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.71
4/21/2017	1610	Water	Drainage South of Trail	38.7026	-120.8183	8.54
4/21/2017	1613	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.86
4/21/2017	1617	Water	Pond North of Trail	38.7027	-120.819	12.61
5/23/2017	1005	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
5/23/2017	0952	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
5/23/2017	0950	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
5/23/2017	0956	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.84
5/23/2017	1020	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
5/23/2017	1016	Visual	Drainage South of Trail	38.7026	-120.8183	-
5/23/2017	1019	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
5/23/2017	1016	Visual	Pond North of Trail	38.7027	-120.819	-
6/26/2017	1232	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
6/26/2017	1231	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
6/26/2017	1231	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
6/26/2017	1236	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
6/26/2017	1243	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
6/26/2017	1244	Visual	Drainage South of Trail	38.7026	-120.8183	-
6/26/2017	1244	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
6/26/2017	1245	Visual	Pond North of Trail	38.7027	-120.819	-
7/26/2017	0944	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
7/26/2017	0945	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
7/26/2017	0946	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
7/26/2017	0952	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
7/26/2017	1003	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
7/26/2017	1002	Visual	Drainage South of Trail	38.7026	-120.8183	-
7/26/2017	1002	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
7/26/2017	1001	Visual	Pond North of Trail	38.7027	-120.819	-

8/28/2017	1012	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
8/28/2017	1015	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
8/28/2017	1014	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
8/28/2017	1016	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
8/28/2017	1000	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
8/28/2017	0958	Visual	Drainage South of Trail	38.7026	-120.8183	-
8/28/2017	0959	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
8/28/2017	0958	Visual	Pond North of Trail	38.7027	-120.819	-
9/20/2017	1248	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
9/20/2017	1242	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
9/20/2017	1241	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
9/20/2017	1243	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
9/20/2017	1255	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
9/20/2017	1256	Visual	Drainage South of Trail	38.7026	-120.8183	-
9/20/2017	1257	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
9/20/2017	1258	Visual	Pond North of Trail	38.7027	-120.819	-
10/31/2017	1301	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
10/31/2017	1258	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
10/31/2017	1257	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
10/31/2017	1259	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
10/31/2017	1309	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
10/31/2017	1310	Visual	Drainage South of Trail	38.7026	-120.8183	-
10/31/2017	1310	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
10/31/2017	1309	Visual	Pond North of Trail	38.7027	-120.819	-
11/28/2017	1535	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	9.58
11/28/2017	1524	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	12.63
11/28/2017	1521	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	7.74
11/28/2017	1527	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.35
11/28/2017	1447	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.34
11/28/2017	1448	Visual	Drainage South of Trail	38.7026	-120.8183	-
11/28/2017	1449	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
11/28/2017	1453	Water	Pond North of Trail	38.7027	-120.819	12.35
12/20/2017	1339	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-

12/20/2017	1334	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
12/20/2017	1333	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
12/20/2017	1334	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
12/20/2017	1357	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	7.98
12/20/2017	1358	Visual	Drainage South of Trail	38.7026	-120.8183	-
12/20/2017	1359	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
12/20/2017	1403	Water	Pond North of Trail	38.7027	-120.819	12.67
1/29/2018	1028	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	11.95
1/29/2018	1019	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
1/29/2018	1017	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
1/29/2018	1022	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.78
1/29/2018	1038	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.70
1/29/2018	1039	Visual	Drainage South of Trail	38.7026	-120.8183	-
1/29/2018	1040	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	12.22
1/29/2018	1045	Water	Pond North of Trail	38.7027	-120.819	12.91
2/27/2018	1435	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
2/27/2018	1431	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
2/27/2018	1430	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
2/27/2018	1432	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
2/27/2018	1446	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	7.77
2/27/2018	1447	Visual	Drainage South of Trail	38.7026	-120.8183	-
2/27/2018	1448	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	12.17
2/27/2018	1452	Water	Pond North of Trail	38.7027	-120.819	12.74
3/23/2018	1207	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	10.19
3/23/2018	1156	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	12.29
3/23/2018	1155	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	9.51
3/23/2018	1159	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.37
3/23/2018	1216	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	9.25
3/23/2018	1218	Water	Drainage South of Trail	38.7026	-120.8183	9.08
3/23/2018	1220	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	9.14
3/23/2018	1223	Water	Pond North of Trail	38.7027	-120.819	12.77
4/27/2018	1317	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	12.29
4/27/2018	1311	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-

4/27/2018	1310	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
4/27/2018	1312	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
4/27/2018	1328	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.37
4/27/2018	1325	Visual	Drainage South of Trail	38.7026	-120.8183	-
4/27/2018	1331	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
4/27/2018	1335	Water	Pond North of Trail	38.7027	-120.819	-
5/21/2018	1122	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
5/21/2018	1119	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
5/21/2018	1118	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
5/21/2018	1120	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
5/21/2018	1131	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
5/21/2018	1131	Visual	Drainage South of Trail	38.7026	-120.8183	-
5/21/2018	1132	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
5/21/2018	1132	Visual	Pond North of Trail	38.7027	-120.819	-
6/18/2018	1014	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
6/18/2018	1011	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
6/18/2018	1010	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
6/18/2018	1011	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
6/18/2018	1022	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
6/18/2018	1022	Visual	Drainage South of Trail	38.7026	-120.8183	-
6/18/2018	1025	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
6/18/2018	1025	Visual	Pond North of Trail	38.7027	-120.819	-
7/12/2018	1358	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
7/12/2018	1351	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
7/12/2018	1350	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
7/12/2018	1352	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
7/12/2018	1405	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
7/12/2018	1405	Visual	Drainage South of Trail	38.7026	-120.8183	-
7/12/2018	1405	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
7/12/2018	1406	Visual	Pond North of Trail	38.7027	-120.819	-
8/17/2018	1226	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
8/17/2018	1220	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
8/17/2018	1221	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-

8/17/2018	1219	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
8/17/2018	1232	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
8/17/2018	1233	Visual	Drainage South of Trail	38.7026	-120.8183	-
8/17/2018	1233	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
8/17/2018	1233	Visual	Pond North of Trail	38.7027	-120.819	-
9/19/2018	Wrong date and time stamp	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
9/19/2018	Wrong date and time stamp	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
9/19/2018	Wrong date and time stamp	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
9/19/2018	Wrong date and time stamp	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
9/19/2018	Wrong date and time stamp	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
9/19/2018	Wrong date and time stamp	Visual	Drainage South of Trail	38.7026	-120.8183	-
9/19/2018	Wrong date and time stamp	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
9/19/2018	Wrong date and time stamp	Visual	Pond North of Trail	38.7027	-120.819	-
10/26/2018	1450	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
10/26/2018	1444	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
10/26/2018	1444	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
10/26/2018	1445	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
10/26/2018	1456	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
10/26/2018	1457	Visual	Drainage South of Trail	38.7026	-120.8183	-
10/26/2018	1457	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
10/26/2018	1457	Visual	Pond North of Trail	38.7027	-120.819	-
11/19/2018	1136	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
11/19/2018	1140	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
11/19/2018	1141	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
11/19/2018	1139	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
11/19/2018	1148	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
11/19/2018	1149	Visual	Drainage South of Trail	38.7026	-120.8183	-
11/19/2018	1149	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
11/19/2018	1149	Visual	Pond North of Trail	38.7027	-120.819	-
12/17/2018	1501	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
12/17/2018	1455	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
12/17/2018	1455	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-

12/17/2018	1456	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
12/17/2018	1508	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
12/17/2018	1509	Visual	Drainage South of Trail	38.7026	-120.8183	-
12/17/2018	1509	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
12/17/2018	1518	Water	Pond North of Trail	38.7027	-120.819	12.25
1/23/2019	1546	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	9.70
1/23/2019	1533	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	12.48
1/23/2019	1531	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	8.03
1/23/2019	1536	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.44
1/23/2019	1600	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.47
1/23/2019	1602	Water	Drainage South of Trail	38.7026	-120.8183	8.45
1/23/2019	1603	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.52
1/23/2019	1606	Water	Pond North of Trail	38.7027	-120.819	12.53
2/25/2019	1341	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	11.88
2/25/2019	1333	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
2/25/2019	1332	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
2/25/2019	1335	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.70
2/25/2019	1350	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.76
2/25/2019	1351	Water	Drainage South of Trail	38.7026	-120.8183	8.65
2/25/2019	1353	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.76
2/25/2019	1356	Water	Pond North of Trail	38.7027	-120.819	12.64
3/25/2019	1012	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	12.13
3/25/2019	1004	Water	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	11.93
3/25/2019	1003	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
3/25/2019	1007	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.67
3/25/2019	1025	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.66
3/25/2019	1027	Water	Drainage South of Trail	38.7026	-120.8183	8.70
3/25/2019	1028	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.83
3/25/2019	1032	Water	Pond North of Trail	38.7027	-120.819	12.55
4/24/2019	1312	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-

4/24/2019	1308	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
4/24/2019	1308	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
4/24/2019	1309	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
4/24/2019	1319	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
4/24/2019	1321	Water	Drainage South of Trail	38.7026	-120.8183	8.40
4/24/2019	1323	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	10.01
4/24/2019	1324	Visual	Pond North of Trail	38.7027	-120.819	-
5/31/2019	1247	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	12.17
5/31/2019	1256	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
5/31/2019	1255	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
5/31/2019	1300	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.33
5/31/2019	1229	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.07
5/31/2019	1226	Visual	Drainage South of Trail	38.7026	-120.8183	-
5/31/2019	1225	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	11.55
5/31/2019	1232	Water	Pond North of Trail	38.7027	-120.819	12.17
6/19/2019	1147	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
6/19/2019	1150	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
6/19/2019	1151	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
6/19/2019	1149	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
6/19/2019	1123	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
6/19/2019	1124	Visual	Drainage South of Trail	38.7026	-120.8183	-
6/19/2019	1124	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
6/19/2019	1123	Visual	Pond North of Trail	38.7027	-120.819	-
7/10/2019	1007	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
7/10/2019	1011	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
7/10/2019	1010	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
7/10/2019	1012	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
7/10/2019	1025	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
7/10/2019	1026	Visual	Drainage South of Trail	38.7026	-120.8183	-
7/10/2019	1026	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
7/10/2019	1025	Visual	Pond North of Trail	38.7027	-120.819	-
8/19/2019	1045	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
8/19/2019	1042	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-

8/19/2019	1041	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
8/19/2019	1043	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
8/19/2019	1054	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
8/19/2019	1055	Visual	Drainage South of Trail	38.7026	-120.8183	-
8/19/2019	1055	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
8/19/2019	1054	Visual	Pond North of Trail	38.7027	-120.819	-
9/20/2019	1526	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
9/20/2019	1424	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
9/20/2019	1423	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
9/20/2019	1425	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
9/20/2019	1531	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
9/20/2019	1532	Visual	Drainage South of Trail	38.7026	-120.8183	-
9/20/2019	1532	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
9/20/2019	1531	Visual	Pond North of Trail	38.7027	-120.819	-
10/28/2019	1250	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
10/28/2019	1246	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
10/28/2019	1246	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
10/28/2019	1247	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
10/28/2019	1307	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
10/28/2019	1306	Visual	Drainage South of Trail	38.7026	-120.8183	-
10/28/2019	1306	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
10/28/2019	1306	Visual	Pond North of Trail	38.7027	-120.819	-
11/18/2019	1504	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
11/18/2019	1433	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
11/18/2019	1433	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
11/18/2019	1434	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
11/18/2019	1450	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
11/18/2019	1451	Visual	Drainage South of Trail	38.7026	-120.8183	-
11/18/2019	1451	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
11/18/2019	1450	Visual	Pond North of Trail	38.7027	-120.819	-
12/4/2019	1414	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	8.55
12/4/2019	-	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
12/4/2019	1407	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-

12/4/2019	1408	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
12/4/2019	1431	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
12/4/2019	1431	Visual	Drainage South of Trail	38.7026	-120.8183	-
12/4/2019	1432	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
12/4/2019	1435	Water	Pond North of Trail	38.7027	-120.819	11.69
1/27/2020	1156	Water	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	11.53
1/27/2020	1146	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
1/27/2020	1146	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
1/27/2020	1150	Water	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	12.25
1/27/2020	1449	Water	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	8.18
1/27/2020	1452	Water	Drainage South of Trail	38.7026	-120.8183	8.07
1/27/2020	1453	Water	Bike Trail Culvert Inlet	38.7025	-120.8185	8.27
1/27/2020	1500	Water	Pond North of Trail	38.7027	-120.819	12.24
2/20/2020	0946	Visual	Stormdrain Manhole on South Edge of Truck Street	38.7026	-120.8154	-
2/20/2020	0942	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 54 and Near Concrete Structure	38.7016	-120.8144	-
2/20/2020	0942	Visual	Drainage on Southeast Corner of Bradley and Throwitaway Way Upstream of Item 64	38.7014	-120.8143	-
2/20/2020	0943	Visual	Drainage Inlet on Southeast Corner of Bradley and Throwitaway Way	38.7017	-120.8145	-
2/20/2020	1021	Visual	Western Drainage Along Lindeman Property South of Detention Pond	38.7027	-120.8183	-
2/20/2020	1020	Visual	Drainage South of Trail	38.7026	-120.8183	-
2/20/2020	1019	Visual	Bike Trail Culvert Inlet	38.7025	-120.8185	-
2/20/2020	1020	Visual	Pond North of Trail	38.7027	-120.819	-

pH readings were collected using a HANNA Model HI 991300 portable meter

(-) Means no sample was collected either because no water was present or there was not enough water to sample